COLDMASTER® INSTRUCTIONS

How To Freeze/Use:

- 1. Before initial use, clean Coldmaster® unit in commercial dishwasher or wash with hot water and mild detergents. Unit should be thoroughly dried.
- 2. For optimum performance, freeze unit at 0°F (-18°C) for a minimum of 8 hours.
- 3. Fill the **Coldmaster**® unit with **refrigerated** product that is at or below 40°F (4°C). **Coldmaster**® units, with the exception of the Coldbowl, will then maintain a temperature below 40°F (4°C) for a minimum of 8 hours. This 40°F (4°C) temperature is based on a 76°F/24°C ambient room temperature.

When using all Coldpans: These units will maintain 40°F (4°C) or below for 8 hours. When using Coldcrock CM1030: Maintains below 40°F (4°C) temperature for 8 hours. May be placed on enclosed Coaster to catch condensation.

When using Coldbowl CM1050: This unit will maintain below $40^{\circ}F$ ($4^{\circ}C$) for up to 5 hours.

- 4. After use, commercial dishwashing is both safe and recommended. May be washed with hot water and mild detergents. Unit should be thoroughly dried.
- 5. Refreeze for 8 hours. This "re-charges" the coolant formula for another 8 hours of service.

NOTE:

- DO NOT HEAT UNITS IN OVEN OR PLACE ON TOP OF BURNERS.
- Although the **refrigerant gel** is non-toxic, it is **not intended** for human **consumption**.

For more information on our **Coldmaster**[®] line, please refer to our **Coldmaster**[®] brochure or full service catalog.

U.S. PATENT NO. 4,981,234

Worldwide Headquarters: P.O. Box 53006 Oklahoma City, Oklahoma 73152-3006 (405) 475-5600 • FAX (405) 475-5607 1-800-654-8210 www.carlislefsp.com

European Distribution Center: Edisonstraat 84, P.O. Box 110 6900 AC Zevenaar, The Netherlands Tel +31/(0)316-596550 • Telex 45642 FAX +31/(0)316-340168 #104803831 Rev. 3/03

